


**HARNESSES
DICKEY**

2-1-05
10/628,763.

... cffc



January 31, 2005

Express Mail Label
No. EV 570 163 049 US

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Re: U.S. Patent No. 6,837,535
Issued January 4, 2005
For: Convertible Roof System
Frank Plesternings, Inventor

Certificate
FEB 08 2005
of Correction

Dear Sir:

We have noted, in proofreading the subject patent, the errors listed on the enclosed Certificate of Correction form. Our records indicate that these errors were made by our office and the Patent Office. Please charge any fee due to Deposit Account No. 50-0275. A duplicate copy of this letter is enclosed.

The corresponding location in the application of the errors in question is as follows:

The first error appears on page 8, line 1 in the application.

The second error appears on page 9, line 6 in the application.

The third error appears on page 9, line 20 (first occurrence) in the application.

The fourth error appears on page 10, line 16 in the application.

The fifth error appears on page 11, line 17 (first occurrence) in the application.

EV 570 163 049 US

P.O. Box 828
Bloomfield Hills, MI 48303 U.S.A.

FOR COURIER DELIVERY ONLY
5445 Corporate Drive
Troy, Michigan 48098
248.641.1600

CABLE
Patents Troy, Michigan
Telex No. & Reply
287637 Harness UR
Telefacsimile 248.641.0270

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.

www.hdp.com

11 FEB 2005


Page 2

The sixth error appears on page 13, line 16 in the application.

Please certify the enclosed Certificate of Correction and return same to us.

Very truly yours,

By

A handwritten signature in black ink, appearing to read 'Chl Blair', written over a horizontal line.

Charles H. Blair
Registration No. 19734
(Attorney for Applicant)

CHB/d
5362-000472

11 FEB 2005

HARNESSES
DICKEY



January 31, 2005

Express Mail Label
No. EV 570 163 049 US

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Re: U.S. Patent No. 6,837,535
Issued January 4, 2005
For: Convertible Roof System
Frank Plesternings, Inventor

Dear Sir:

We have noted, in proofreading the subject patent, the errors listed on the enclosed Certificate of Correction form. Our records indicate that these errors were made by our office and the Patent Office. Please charge any fee due to Deposit Account No. 50-0275. A duplicate copy of this letter is enclosed.

The corresponding location in the application of the errors in question is as follows:

The first error appears on page 8, line 1 in the application.

The second error appears on page 9, line 6 in the application.

The third error appears on page 9, line 20 (first occurrence) in the application.

The fourth error appears on page 10, line 16 in the application.

The fifth error appears on page 11, line 17 (first occurrence) in the application.

P.O. Box 828
Bloomfield Hills, MI 48303 U.S.A.

FOR COURIER DELIVERY ONLY
5445 Corporate Drive
Troy, Michigan 48098
248.641.1600

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.

CABLE
Patents Troy, Michigan
Telex No. & Reply
287637 Harness UR
Telefacsimile 248.641.0270

www.hdp.com

11 FEB 2005


11 FEB 2005

The sixth error appears on page 13, line 16 in the application.

Please certify the enclosed Certificate of Correction and return same to us.

Very truly yours,

By

A handwritten signature in black ink, appearing to read "CH Blair", written over a horizontal line.

Charles H. Blair
Registration No. 19734
(Attorney for Applicant)

CHB/d
5362-000472

11 FEB 2008

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,837,535

Page 1 of 1

DATED : January 4, 2005

INVENTOR(S) : Frank Plesterings

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 7, "bridge portion 140" should be -- bridge portion 142 --.

Column 4, line 42, "retaining" should be -- retain --.

Column 4, line 59 (second occurrence), after "plate" delete "to ".

Column 5, line 17, "moved" should be -- move --.

Column 5, line 48 (first occurrence), "in" should be -- and --.

Column 6, line 38, "rotated" should be -- rotate --.

MAILING ADDRESS OF SENDER: Harness, Dickey & Pierce, P.L.C.
P.O. Box 828
Bloomfield Hills, MI 48303

PATENT NO. 6.837.535

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

11 FEB 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,837,535

Page 1 of 1

DATED : January 4, 2005

INVENTOR(S) : Frank Plesternings

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4, line 7, "bridge portion 140" should be -- bridge portion 142 --.

Column 4, line 42, "retaining" should be -- retain --.

Column 4, line 59 (second occurrence), after "plate" delete "to ".

Column 5, line 17, "moved" should be -- move --.

Column 5, line 48 (first occurrence), "in" should be -- and --.

Column 6, line 38, "rotated" should be -- rotate --.

MAILING ADDRESS OF SENDER: Harness, Dickey & Pierce, P.L.C.
P.O. Box 828
Bloomfield Hills, MI 48303

PATENT NO. 6,837,535

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

11 FEB 2005